



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Yukio TOYOZAWA, et al.

Application No.: 10/758,037

Confirmation No.: 6132

Filed: January 16, 2004

U.S. Patent No.: 6,859,007

Issued: February 22, 2005

For:

SERVO MOTOR DRIVE CONTROL DEVICE

ATTENTION

BRANCH

CERTIFICATE OF CORRECTION

Certificate JUL 1 9 2005 of Correction

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistakes shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Registration No. 28,607

1201 New York Ave, N.W., Suite 700

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

· RT. O STORE

PTO/SB/ 44 (08-00)
Approved for use through 09/30/2000. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,859,007

(Also Form PTO-1050)

DATED: February 22, 2005

INVENTOR(S): Yukio TOYOZAWA, et al.

On the title page, at item (73), please change –Fanuc Ltd-- to –FANUC LTD-- Column 7, line 18, please change " $\theta(c)$ " to – $\epsilon(c)$ --. Column 8, line 50,after the word "thereto", please delete --.-. Column 10, line 51, please change "(FIG. 1C)" to –(FIG. 11C)--.

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP 1201 New York Ave., N.W. Suite 700 Washington, DC 20005 PATENT NO. 6,859,007

No. of add'l copies @ 50¢ per page

Ψ

BC : 9 2008

